



This is a case study of a site that had issues with a clogging leachate collection system. The data presents the story over a 3-year span detailing how the issue was detected, the solutions the site tried, the impact of the issues on the GCCS, and ultimately how the site got back on track through the innovative electronic descaling units they installed.



Weather Data

	Avg Temp (deg. F)	Rainfall (in.)		Avg Temp (deg. F)	Rainfall (in.)
Jan-16	28	0.88	Nov-16	45	0.8
Feb-16	34	3.23	Dec-16	34	1.83
Mar-16	49	3.48	Jan-17	37	3.32
Apr-16	52	3.68	Feb-17	43	2.04
May-16	60	3.25	Mar-17	43	5.78
Jun-16	72	4.4	Apr-17	59	4.59
Jul-16	74	3.24	May-17	64	3.73
Aug-16	76	4.24	Jun-17	71	3.58
Sep-16	70	4.03	Jul-17	71	10.46
Oct-16	57	1.93	Aug-17	69	1.28

Want to know more about the electronic descaling units?

Green Industry Innovations Group
416.681.3007
info@giigroup.ca
www.giiscalecontrol.com

gii scale control

gii group
Green Industry Innovations Group